

## URGENT Field Safety Notice

### Philips Azurion System R2.2.0, R2.2.1, R2.2.3, R2.2.5 and R2.2.6 Potential Loss of X-ray Functionality

16 March 2023

**This document contains important information for the continued safe and proper use of your equipment**

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

Please retain this letter for your records.

Dear Customer,

Philips has become aware of a potential safety issue with the Philips Azurion System R2.2.0, R2.2.1, R2.2.3, R2.2.5 and R2.2.6, where the system may exhibit a loss of X-Ray functionality. This URGENT Field Safety Notice is intended to inform you about:

#### **1. What the issue is and under what circumstances it can occur**

Philips has identified a potential safety issue where the Philips Azurion system may unexpectedly lose X-ray functionality.

Due to a software issue, a mechanism that is present in the system to manage the number and size of Log Trace Files does not function properly. Without this mechanism, the Log Trace Files created by the system (e.g., at start, during use) may occupy the full disk capacity of the Philips Azurion system.

When the full disk capacity is reached, X-Ray functionality will cease to be available without an advance warning to the user.

Based on system usage, the time until the disk will be full may vary. Based on our testing, if the system is started once a day, the disk will not become full before 525 days of use. If a system is started multiple times a day, the disk will not become full before 421 days of use.

Note: When a new software release is installed in the system, all existing Log Trace Files are deleted. Therefore, the above-mentioned timelines should be considered as from the date that the software release (R2.2.0, 2.2.1, 2.2.3, 2.2.5 or R2.2.6) was installed in the Philips Azurion system.

#### **2. Hazard/harm associated with the issue**

If this issue occurs, the X-ray functionality of the system will not be available. If the problem occurs during a procedure, there will be a sudden interruption of the procedure.

To date, Philips has not received any complaints related to this issue.

### 3. Affected products and how to identify them

The Azurion series (within the limits of the operation room table) are intended for use to perform:

- Image guidance in diagnostic, interventional, and minimally invasive surgery procedures for the following clinical application areas: vascular, non-vascular, cardiovascular, and neuro procedures.
- Cardiac imaging applications including diagnostics, interventional and minimally invasive surgery procedures.

Additionally:

- The Azurion series can be used in a hybrid operating room.
- The Azurion series contains several features to support a flexible and patient-centric procedural workflow.

The following systems with software release R2.2.0, R2.2.1, R2.2.3, R2.2.5 and R2.2.6 are affected:

System product name	Model number
Azurion 3M12	722063, 722221
Azurion 3M15	722064, 722222
Azurion 5M12	722227
Azurion 5M20	722228
Azurion 7B12/12	722067, 722225
Azurion 7B20/15	722068, 722226
Azurion 7M12	722078, 722223
Azurion 7M20	722079, 722224

The system product name and model number can be found on the System Identification Label located on the system stand (Figure 1).




Figure 1: System identification

The software version of the Philips Azurion system can be identified during start-up (Figure2).




Figure 2: System start-up screen

Philips is sending this notification directly to customers that have (an) affected system(s).

#### 4. Actions that should be taken by the customer / user in order to prevent risks for patients or users

- Keep this Field Safety Notice with the documentation of the system until Philips corrects your system.
- Circulate this notice to all users of the system so that they are aware of the issue.
- Return the attached reply form to Philips to confirm that the users of the system have reviewed and understood this Field Safety Notice.

#### 5. Actions planned by Philips IGT Systems [SRN: NL-MF-000001489] to correct the problem

Philips is working on a software release that will correct this issue (reference FCO72200528). In the interim, until this software is available and installed in your affected system(s), Philips will be removing the Log Trace Files from the affected systems to free up disk capacity (reference FCO72200529).

Philips will be prioritizing these activities based on the time the affected software release has been installed in the Philips Azurion system. You will be contacted by your local Philips representative to schedule these activities.

If you need any further information or support concerning this issue, please contact your local Philips representative.

This notice has been reported to the appropriate Regulatory Agencies.

Philips regrets any inconvenience caused by this matter.

Sincerely,

  
Marjan Vos  
Head of Quality – IGT Systems

## URGENT Field Safety Notice Response Form

### Reference: Potential Loss of X-ray Functionality

**Instructions:** Please complete and return this form to Philips promptly and no later than 30 days from receipt. Completing this form confirms receipt of the Urgent Field Safety Notice, understanding of the issue, and required actions to be taken.

Customer/Consignee/Facility Name: \_\_\_\_\_

Street Address: \_\_\_\_\_

City/State/ZIP/Country: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

### Customer Actions:

- Keep the Field Safety Notice with the documentation of the system until Philips corrects your system.
- Circulate the notice to all users of the system so that they are aware of the issue.

We acknowledge receipt and understanding of the accompanying Urgent Field Safety Notice and confirm that the information from this letter has been properly distributed to all users that handle the Philips Azurion system.

### Name of person completing this form:

Signature: \_\_\_\_\_

Printed Name: \_\_\_\_\_

Title: \_\_\_\_\_

Telephone Number: \_\_\_\_\_

Email Address: \_\_\_\_\_

Date (DD / MMM / YYYY): \_\_\_\_\_

<provide instructions here for the customer regarding returning the form to Philips, e.g. fax #, email address. For example, "Please fax this completed form to Philips at (xxx)xxx-xxxx">