

URGENT Field Safety Notice

Azurion and Allura Xper series

Potential for Loss of Mechanical Movements and FlexMove Carriage with C-Arc Assembly to Fall

05-June-2023

<To: Name / Title / Customer Name
Street Address
City, State, Zip Code
<modify title block format as needed>

This document contains important information for the continued safe and proper use of your device

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

Please retain this letter for your records.

Dear Customer,

Philips has identified a potential safety issue with Azurion and Allura Xper systems installed with the FlexMove option, which could pose a risk for patients and bystanders. This URGENT Field Safety Notice is intended to inform you about:


1. What the problem is and under what circumstances it can occur

Philips has identified that due to the forces applied during the movement of the C-Arc of the Azurion and Allura systems, the bolts supporting the FlexMove Carriage may become loose and/or break, and cracks may appear in the FlexMove Carriage (see Figures 1, 2 and 3).

If FlexMove rail fixation bolts become loose or broken, or cracks appear in the carriage, the following issues may occur:

- Transversal movements of the C-Arc stop due to false collision detections because of additional friction.
- Manual movement of the FlexMove Carriage not possible due to added friction.
- Abnormal noise during transversal movement of the C-Arc.
- Unstable C-Arc suspension.
- Fall of the C-Arc Assembly (1,500 kg), if all bolts in the X-axis would break/get loose.
- Drop of the C-Arc Assembly (up to 10cm if C- Arc is at one side of the rail, up to 5 cm if C-Arc is in the center of the rails, and 1.5 cm if the C-Arc is in the Anterior/Posterior position), if all bolts in the Y-axis would break/get loose.

As of May 2023, Philips has received fourteen (14) complaints related to eleven (11) systems reporting loose and/or broken bolts. In three (3) cases cracks were also identified. In none of these cases the C-Arc Assembly fell or dropped. No harm to patients or bystanders was reported.



FlexMove Carriage Assembly

Cracks may appear in one or more of the corners around the tie strap as seen in the photo below (4 places on each side)




Figure 2

C-Arc Assembly

Figure 1




Figure 3

Indication of 4 locations on (each side of) the X-axis rail of the FlexMove Carriage where cracks may occur.

2. Hazard/harm associated with the issue

Loss of the mechanical movements of the C-Arc Assembly during a procedure may result in a delay and/or abortion of the procedure.

Although the likelihood of serious injury or death is considered to be remote, it cannot be ruled out that the FlexMove Carriage with C-Arc Assembly could drop or fall, which may cause different levels of injury, potentially serious injury or death to the patient and/or bystander.

3. Affected products and how to identify them

Identification of affected systems

All Azurion and Allura Xper systems installed with the FlexMove option are affected by this issue.

A list of affected systems is provided in Appendix A of this notification. Affected systems can be identified by their Product Description, Product Code, and Serial Number (SN), which can be found on the System Identification Label, as shown below.




Figure 4. Picture of System Identification Label (Example of Allura)




Figure 5. Location of System Identification Label on the systems

Philips is sending this notification directly to customers that have (an) affected system(s).

Intended Use

The Azurion series (within the limits of the operation room table) are intended for use to perform:

- Image guidance in diagnostic, interventional, and minimally invasive surgery procedures for the following clinical application areas: vascular, non-vascular, cardiovascular, and neuro procedures.
- Cardiac imaging applications including diagnostics, interventional and minimally invasive surgery procedures.

The Allura Xper series are intended for use on human patients to perform:

- Vascular, cardiovascular and neurovascular imaging applications, including diagnostic, interventional and minimally invasive procedures. This includes peripheral, cerebral, thoracic and abdominal angiography, as well as PTAs, stent placements, embolizations and thrombolysis.
- Cardiac imaging applications including diagnostics, interventional and minimally invasive procedures (such as PTCA, stent placing, atherectomies), pacemaker implantations, and electrophysiology (EP).
- Non-vascular interventions such as drainage, biopsies and vertebroplasties procedures.

The Azurion and the Allura Xper series may be configured with the FlexMove Carriage.

FlexMove allows parking the stand in a stand-by position and then moving it into position when needed during the procedure. If a FlexMove Carriage is installed, the stand moves longitudinally and transversely on ceiling-mounted rails.

4. Actions that should be taken by the customer / user in order to prevent risks for patients and bystanders

- Keep this Urgent Field Safety Notice with the documentation of the system until Philips corrects your system. Ensure the letter is in a place likely to be seen/viewed.
- In case of cracks in the FlexMove Carriage (see Figures 2 and 3), please contact Philips so that inspection of your system can be prioritized.
- In case of abnormal noise during transversal movements of the C-Arc, please contact Philips so that inspection of your system can be prioritized.
- Please circulate this Urgent Field Safety Notice to all users so that they are aware of the issue.
- Please complete and return the attached response form (on page 9) to Philips promptly and no later than 30 days from receipt. Completing this form confirms receipt of the Urgent Field Safety Notice and understanding of the issue and required actions to be taken.

5. Actions planned by Philips IGT-Systems (SRN: NL-MF-000001489) to correct the problem

Philips will inspect all affected systems to:

- Check if there are cracks in the FlexMove Carriage
- Check if the FlexMove Carriage's bolts are secured properly
- Replace any loose bolts and broken bolts.

Philips will contact you to schedule a visit to inspect your system(s) (reference FCO72200538). This inspection is of great importance, as it will allow Philips to check if the issue described in this letter is present in your system. We therefore ask your collaboration to prioritize scheduling this inspection.

If, during the inspection, it is not possible to replace the identified loose or broken bolt(s), or if cracks are identified, Philips will plan for the replacement of the affected bolts and/or FlexMove Carriage.

Based on available information, systems may safely continue to be used for at least one year following these actions. Our technical experts are working on a permanent solution with the highest priority, and Philips will implement this solution in your system as soon as possible. We appreciate your cooperation in complying with the instructions provided in this letter.

If you need any further information or support concerning this matter, please contact your local Philips representative: *<Philips representative contact details to be completed by the Market/Business>*

This notice has been reported to the appropriate Regulatory Agencies.

Philips regrets any inconvenience caused by this matter.

Sincerely,



Marjan Vos
Senior Director Quality IGT Systems

Appendix A

Product Code	Product Description	Serial Number
722010	Allura Xper FD10	1060, 1163, 1164, 1364
722012	Allura Xper FD20	1014, 1019, 1034, 1054, 1063, 1077, 1113, 1187, 1212, 1218, 1219, 1229, 1254, 1306, 1327, 1333, 1335, 1337, 1344, 1356, 1369, 1399, 1406, 1433, 1439, 1504, 1537, 1555, 1589, 1633, 1676, 1683, 1726, 1746, 1803, 1806, 1844, 1850, 1853, 1904, 1908, 1909, 1922, 2003, 2071, 2076, 2086, 2089, 2108, 2215, 2219, 2282, 2338, 2417, 2466, 2594, 2875, 600, 651, 672, 735, 740, 760, 766, 852, 854, 863, 893, 908, 920, 921, 959, 963, 972, 986, 990
722022	Allura Xper FD10 OR Table	6
722023	Allura Xper FD20 OR Table	101, 102, 103, 105, 106, 107, 108, 109, 110, 112, 113, 116, 117, 118, 119, 12, 121, 122, 124, 125, 126, 127, 128, 129, 13, 130, 132, 133, 134, 135, 137, 138, 14, 141, 142, 144, 145, 149, 150, 152, 158, 159, 160, 164, 165, 169, 177, 18, 2, 20, 25, 27, 31, 34, 35, 4, 41, 42, 46, 49, 5, 50, 52, 53, 58, 60, 63, 64, 65, 67, 68, 69, 70, 71, 72, 75, 8, 82, 83, 85, 86, 87, 88, 9, 90, 94, 96, 98
722026	Allura Xper FD10	166, 529, 619, 1116, 1133
722028	Allura Xper FD20	1001, 1011, 1029, 1038, 1049, 1055, 1074, 1088, 1094, 1130, 1181, 1214, 1256, 1258, 1267, 1269, 128, 139, 1456, 1474, 1538, 1546, 1547, 155, 1593, 1598, 1623, 1624, 1647, 1652, 1662, 1699, 1736, 1790, 1838, 1844, 1877, 193, 1955, 2020, 210, 214, 2143, 216, 217, 2198, 2208, 2305, 2306, 233, 2340, 2372, 2436, 2460, 2482, 251, 2536, 254, 260, 2745, 278,

		2924, 30, 300, 310, 313, 315, 326, 333, 376, 38, 381, 406, 431, 444, 456, 460, 462, 485, 491, 494, 496, 498, 499, 505, 520, 528, 539, 556, 588, 589, 604, 617, 637, 657, 668, 669, 670, 672, 692, 710, 720, 748, 758, 768, 796, 802, 815, 820, 889, 895, 896, 9, 901, 910, 911, 919, 926, 930, 932, 940, 942, 952, 956, 972, 974, 975, 99
722033	Allura Xper FD10 OR Table	1
722035	Allura Xper FD20 OR Table	1, 10, 100, 101, 102, 104, 106, 107, 108, 109, 11, 110, 111, 113, 114, 116, 117, 118, 119, 12, 121, 123, 124, 125, 126, 127, 128, 129, 13, 131, 132, 134, 142, 143, 144, 145, 146, 148, 151, 153, 154, 156, 158, 163, 164, 165, 166, 167, 168, 17, 171, 172, 174, 177, 183, 184, 185, 186, 19, 190, 191, 194, 195, 196, 198, 200, 201, 202, 203, 204, 206, 207, 208, 21, 212, 215, 218, 222, 226, 229, 23, 230, 231, 233, 236, 24, 242, 243, 245, 246, 248, 25, 250, 252, 253, 254, 255, 256, 258, 259, 26, 263, 265, 28, 29, 30, 31, 32, 34, 35, 38, 40, 43, 45, 46, 47, 48, 49, 52, 53, 56, 57, 58, 59, 6, 60, 61, 62, 63, 64, 65, 69, 70, 71, 72, 74, 75, 76, 77, 78, 79, 82, 83, 84, 85, 88, 89, 92, 93, 94, 95, 96, 97, 98, 99
722079	Azurion 7 M20	1017, 1023, 1034, 1042, 1045, 1053, 1104, 1139, 1230, 1242, 1255, 1318, 217, 225, 229, 233, 234, 235, 239, 24, 25, 255, 256, 262, 281, 282, 285, 286, 287, 288, 296, 302, 31, 313, 316, 317, 32, 328, 329, 333, 335, 337, 34, 341, 346, 35, 352, 354, 356, 357, 360, 364, 369, 378, 379, 381, 389, 390, 397, 398, 399, 40, 400, 405, 408, 420, 422, 423, 428, 43, 437, 438, 450, 452, 453, 460, 463, 47, 470, 482, 483, 484, 487, 491,

		492, 493, 498, 500, 524, 533, 541, 546, 551, 557, 56, 561, 564, 574, 578, 595, 608, 621, 628, 635, 644, 651, 66, 684, 686, 694, 697, 703, 703339, 703365, 703404, 703475, 703529, 703549, 703636, 703661, 703690, 703804, 703872, 703897, 703918, 703922, 704008, 704060, 704146, 704149, 704237, 713, 716, 720, 722, 740, 745, 747, 75, 752, 764, 77, 778, 793, 794, 810, 814, 819, 831, 832, 833, 838, 840, 856, 857, 874, 879, 900, 902, 912, 939, 941, 942, 944, 969, 980, 990
722224	Azurion 7 M20	1053, 1054, 1080, 1285, 1361, 156, 1568, 187, 213, 345, 37, 491, 509, 532, 559, 596, 7, 707, 782, 785, 841, 874, 875, 9

URGENT Field Safety Notice Response Form

Reference: Potential for Loss of Mechanical Movements and FlexMove Carriage with C-Arc Assembly to Fall, FlexMove Carriage (used with Azurion and Allura Xper systems), and FCO 72200538.

Instructions: Please complete and return this form to Philips promptly. Completing this form confirms receipt of the URGENT Field Safety Notice, understanding of the issue, and required actions to be taken.

Customer/Consignee/Facility Name: _____

Street Address: _____

City/State/ZIP/Country: _____

Customer Actions:

- Keep the Urgent Field Safety Notice with the documentation of the system until Philips corrects your system. Ensure the letter is in a place likely to be seen/viewed.
- In case of cracks in the FlexMove Carriage, please contact Philips so that inspection of your system can be prioritized.
- In case of abnormal noise during transversal movements of the C-Arc, please contact Philips so that inspection of your system can be prioritized.
- Please circulate the Urgent Field Safety Notice to all users so that they are aware of the issue.
- Please complete and return this response form to Philips promptly and no later than 30 days from receipt. Completing this form confirms receipt of the Urgent Field Safety Notice and understanding of the issue and required actions to be taken.

We acknowledge receipt and understanding of the accompanying Urgent Field Safety Notice and confirm that the information from this letter has been properly distributed to all users that handle the affected Philips Allura / Azurion system(s).

Name of person completing this form:

Signature: _____

Printed Name: _____

Title: _____

Telephone Number: _____

Email Address: _____

Date (DD / MMM / YYYY): _____

It is important that your organization acknowledges receipt of this letter. Your organization's reply is the evidence required to monitor the progress of this Field Safety Corrective Action.

<provide instructions here for the customer regarding returning the form to Philips, e.g. fax #, email address. For example, "Please fax this completed form to Philips at (xxx)xxx-xxxx">

