

**URGENT FIELD CORRECTIVE ACTION**

**Urgent Field Safety Notice – Revohem™ ADP - Ref AP200422- Lot FA1958 -  
Inadequate packaging of Revohem™ ADP boxes**

Dear Customers, Healthcare Professional,  
cc: Chairman Medical Board and relevant Head of Departments

This letter is to inform you concerning the issue of the below mentioned lot of Revohem™ ADP - Ref AP200422- Lot FA1958 - Inadequate packaging of Revohem™ ADP boxes.

Product Name:	Revohem™ ADP
Product Identifier.:	AP200422
Material Code:	ZPS01436
Affected Lot:	Lot: FA1958
Basic UDI-DI:	366353700049BK
Intended Use:	For in-vitro diagnostic use Measurement of platelet aggregation
Product Owner:	HYPHEN BioMed
Product Owner Address:	ZAC Neuville sur Oise – 155 rue d'Eragny – 95000 NEUVILLE SUR OISE (France)
Associated Adverse Event in Singapore:	Not applicable

**Problem Description**

Please refer to the attached Urgent Field Safety Notice dated on 20 March 2023 issued by HYPHEN BioMed for more detailed information.

Action to be taken

1. Please follow the actions to be taken stated under Urgent Field Safety Notice dated 20 March 2023 issued by HYPHEN BioMed.
2. Please complete and return the SYSMEX CUSTOMER ACKNOWLEDGEMENT FORM\_CN-2022-07.
3. Please disseminate the letter to relevant people within your organization.

Contact Reference

If you have question concerning this information, please contact our local Sysmex Representative. We would be glad to assist you further.

We deeply apologize for any inconvenience caused, and we thank you for your kind patience and continued support.

Yours Sincerely



---

Kelvin Fan

Manager

Quality Management

Sysmex Asia Pacific